
From: Michael J Winters (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC1082]
Sent: 4/15/2015 3:41:57 PM
To: Doug Wight (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Dougla7]
Subject: FW: Ash Pond ABC inspection 04/14/15
Attachments: 20150414123307440.pdf

From: Jeffrey R Marcell (Generation - 3)
Sent: Tuesday, April 14, 2015 12:35 PM
To: Michael J Winters (Generation - 34)
Cc: John Cima (Generation - 34); Jeffrey C Heffelman (Generation - 3); Kenneth Roller (Services - 6)
Subject: RE: Ash Pond ABC inspection 04/14/15

Attached.

Discharge (seeping/flow into weir) at C Pond, about the same as previous inspection. Standing water around weir.

Standing water behind sand-bags at 'A' with standing water at the toe of the slope. The southern edge of the 'A' pond interior, from the SE corner to the sandbags, continues to hold water.

Current rainfall at time of inspection was 0.18".

Rain events 04/07 – 04/10 totaled 0.35".

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)